

General Environmental Incident Summary

Incident: 3336 **Date/Time Notice:** 6/2/2014 1100 **DEM Incident No:**
Responsible Party: Morcon Construction
Date Incident: 6/1/2014 **Time Incident:** 1500 **Duration:** 8 hours
County: Williams **Twp:** 129 **Rng:** 101 **Sec:** 1 **Qtr:**
Lat: 48.16864 **Long:** -103.63660 **Method:** Address matching
Location Description: 4315 9th Ave. West, Williston ND (Lot 1, Block 1 of Roseland Subdivision)
North and North East corner of development.

Submitted By: Doug Reynolds **Affiliation:** Superintendent
Address: 15 Enery St.
City: Williston **State:** ND **Zip:** 58801

Received By:

Contact Person:

unknown
unknown, MN

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Paint disposal

Description of Released Contaminant: Latex paint

Volume Spilled: 2.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

Painter decided to dispose of extra paint in landscape island and planters

Risk Evaluation:

If not cleaned soon will absorb into soil and work its way into the aquafer.

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Will prevent plant root system from solidfiing in soil and eventually reach the aquafer.

Action Taken or Planned:

We will demand he/she remove product from location through excavation.

Wastes Disposal Location: At an approved site--reciept from painter will be requested.

Agencies Involved:

Updates

Date: 6/2/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted bare soil. Followup is necessary.

Date: 9/30/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Navigated to area through address and GPS monitor. GPS took me to the center of the intersection of 9th Ave W and 4th St. SW of the location was the Good Shepherd Lutheran Church, SE was a new building nearing completion and north of the intersection was an alley-way into a trailer court. Did not observe any planter or paint release at the time of recon. Unless more information is provided, no further follow-up needed at this time.